


CURVE

STAMPATE E A SETTORI


BU


Curva stampata
rm = 1 x Ø



Ød1	α = 90°		α = 60°		α = 45°		α = 30°		α = 15°	
	l	Peso	l	Peso	l	Peso	l	Peso	l	Peso
nom	mm	Kg	mm	Kg	mm	Kg	mm	Kg	mm	Kg
80	105	0.26	58	0.32	41	0.17	27	0.15	13	0.11
100	100	0.31	58	0.33	41	0.21	27	0.18	13	0.15
125	125	0.48	72	0.33	52	0.29	33	0.20	16	0.18
160	160	0.66	92	0.56	66	0.48	43	0.32	21	0.24
200	200	1.12	115	0.82	83	0.80	54	0.62	26	0.35
250	242	1.77	144	1.12	103	1.05	67	0.91	33	0.65


BFU

Curva stampata
rm = 1 x Ø



Ød1	α = 90°		α = 60°		α = 45°		α = 30°		α = 15°	
	l	Peso	l	Peso	l	Peso	l	Peso	l	Peso
nom	mm	Kg	mm	Kg	mm	Kg	mm	Kg	mm	Kg
315	315	3.00	182	2.20	130	1.90	84	1.42	41	0.91
355	355	3.75	205	2.80	147	2.26	95	1.70	47	1.41
400	400	5.64	231	3.47	166	2.96	107	2.27	53	1.70
450	450	7.00	260	4.70	186	4.00	121	3.00	59	2.20